



Project Resources Inc.

Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

Property ID:	2112
Property Address:	4442 MILWAUKEE ST.
Owner:	GREGORIO SOTO
Phone:	31291-1182

Restoration Items in Question:

Item:
Item:
Item:
Item:
Item:
Item:

Additional Comments:


--

- ☒ I agree restoration is completed, except as noted
- ☐ I do not agree restoration is completed
- ☐ I agree that the sprinkler system is working properly following reinstallation by contractor

Gregorio Soto
Owner's Signature Date


Jaime Rys 7/16/05
Contractor's Signature Date

private alley 60x8 D.G.



32x38
D.G.

4x21 D.G. tree stays



6x21 D.G.

Pole

tree stays

tree stays
R.M. 2x2

21x12 Soil

#2112

~~X Fulgencio Soto~~

4442 Milwaukee

no sprinkler system

42x14

SOD

6x2 RM -
owner will remove

piedra grande
mediara
chica
Red Mulch
Brown mulch

driveway gravel

14x12
SOD

Flower bed 15x2 Soil

Leave ↑

23x12
SOD

12x12
tree stays
R.M.

24x12
rose bushes
remove
SOD

5x12
RM

tree stays

Flower bed 12x1 Soil

Flower bed 12x1 Soil

7x7
RM

30x7
R.M.

tree stays

12x7
RM



**U.S. Environmental Protection Agency
Vasquez Boulevard I/70 Superfund Site
Replacement Certificate**



**US Army Corps
of Engineers**
Omaha District

Property Owner Gregorio Soto

Property Address 4442 Milwaukee Street

Property Identification Number 2112

Material Removed	Quantity	Unit Price	Replacement Value
Flower bed area (square feet)			
Trees			
Itemized shrubs/bushes	17	\$12.00	\$204.00
Total			\$204.00

The acceptance of the replacement certificate and the signature below is full acknowledgement by the property owner that this is a fair and reasonable compensation for plant materials removed during remediation activities, but not planted or installed by the government or it's contractors.

The total amount of \$204.00 has been received by the owner in the form of a replacement certificate, # 15037, to be utilized at Paulino's Gardens, 6300 N. Broadway, Denver, CO 80216.

X Gregorio Soto
Property Owner's Signature Date

Jaime Reyes 7/16/05
Contractor's Signature Date

Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name: Gregorio Soto	Phone: 303) 291-1182
---	------------------------------------

Addresses of Properties covered by this Agreement:	Address: 4442 Milwaukee St.
	Address:
	Address:
	Address:

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed, the Grantor will have an opportunity to review and approve the planned soil removal, and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

☐ I grant access to my properties

☐ I do not grant access to my properties

Signature

Date

Signature

Date

☐ I would like to be present during any sampling that is required.

Consento para el Acceso de la Propiedad

DERECHO A ENTRAR LA PROPIEDAD

Otorgante (dueño(a) de propiedad) se da permiso y autoriza la Agencia para la Protección del Medio Ambiente de Los Estado Unidos (EPA) o su representantes autorizado, en conjunto el Cesionario, a entrar y llevar a cabo algunas actividades ambientales acerca de la propiedad descrito que sigue:

Dueño de la Propiedad: Gregorio Soto	Numero Diario:
---	-----------------------

Dirección de Propiedades Cubierto por este Acuerdo:	Dirección: 4442 Milwaukee St.
	Dirección:
	Dirección:

PROPÓSITO DE ACTIVIDADES AMBIENTALES

El EPA solicita el acceso a coleccionar muestras de tierra y remover tierra que tiene alta concentraciones de arsénico y/o plomo que podría ser peligroso a su salud. La tierra estará removido y el(los) área(s) excavado(s) estará reemplazado con materiales limpias y restaurado. Este trabajo estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de EPA se contactará el Otorgante personalmente a discutir el trabajo estar realizado, el Otorgante tendrá la oportunidad a examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termina, el Otorgante estará pedido a revisar el trabajo, confirmar su terminación y cumplir con su aprobación. Después de terminación, el Otorgante recibirá un documento escrito por el EPA que indica la propiedad había sido remediado.

ACCIONES DE LA RESPONDENCIA AMBIENTAL.

Por su firma de este Acuerdo de Acceso, el Otorgante concede el EPA, sus empleos, contratadores y subcontratadores el derecho a entrar la propiedad, en tiempos razonable y sin noticia anterior, para el único propósito a realizar trabajo. Este acceso debería persistir en efecto hasta que el trabajo había sido terminado en un estado aceptado. El Ortorgante también está de acuerdo con:

- Remover obstrucciones que incluye botes, remolque, vehículos, juguetes de niños, montones de madera, casas de perros, etc.
- Remover de bulbos de flores, o otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener reemplazo de vegetación, incluso la aplicación de fertilizante, como es necesario subsecuente de la riega inicial por el EPA, a menos que regando está restringido por la Junta de Agua de Denver.
- Permanecer por la guía de Salud y Seguridad proveído por el EPA;
- Si la propiedad está rentado, asiste el EPA a obtener la aprobación del inquilino para acceso a la propiedad a llevar a cabo el trabajo, si el EPA está inhábil a obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad incluyendo los áreas exterior y interior de edificios.

ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividades o trabajo hecho, o el equipo usado a llevar de cabo los actividades, o hacer cualquier acciones en respecto de la usa de dicho propiedad que podría arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor contacta, el centro de comando de VB/I-70 a (303) 487-0377.

☒ Si yo permito acceso a mi propiedad

☐ No permito acceso a mi propiedad.

Gregorio Soto 3/4/05
Firma Fecha

Firma Fecha

☐ Me gustaría ser presente durante de cualquier colección de muestras.

Property Check-List

Yes/No

1. no Sprinkler System?
2. n/a Basement Photos?
3. yes Photos of Water Meter?
4. yes All 3 Signatures?
5. yes Number of Trees?
6. yes Approximate Voucher Size?
7. yes Are all trees and bushes clearly labeled on the map?
8. n/a Clotheslines marked and is it removed or replaced?
9. yes House accessible for equipment?
10. yes Owner clear of everything they will need to remove?
11. yes Owner clear the dates when we call him are approximate?
12. yes A second walk through done on the property to double check the map by the individual who did the video/photos?

2112 Gregorio Soto
4442 Milwaukee St.



Project Resources Inc.

Property Access Checklist

Property ID: <u>2112</u>	<input type="checkbox"/> WORK STARTED	ON: <u> </u> / <u> </u> / <u> </u>
Property Address: <u>4444 Milwaukee</u>	<input type="checkbox"/> WORK COMPLETED	ON: <u> </u> / <u> </u> / <u> </u>

Property Owner: <u>Gregorio Soto</u>	Property Renter:
Mailing Address:	Home Phone:
	Fax:
	Cell/Pager:
Home Phone: <u>312-291-1182</u>	Additional Information:
Fax:	
Cell/Pager:	

<input checked="" type="checkbox"/> Notification Letter	Sent: <u>3 / 04 / 05</u>	By: <u>M. Redfern</u>
<input checked="" type="checkbox"/> Access Agreement	Signed: <u>03 / 04 / 05</u>	By: <u>Gregorio Soto</u>
<input checked="" type="checkbox"/> Restoration Agreement	Signed: <u>05 / 11 / 05</u>	By: <u>Gregorio Soto</u>
<input type="checkbox"/> Topsoil Sampling (if applicable)	<u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Disposal Sampling (if applicable)	<u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Garden Sampling (if applicable)	<u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Utility Clearance	Called: <u> </u> / <u> </u> / <u> </u>	By:
<input checked="" type="checkbox"/> Video/Photos (Before)	On: <u>05 / 11 / 05</u>	By: <u>M. Fowler / J. Reyes</u>
<input type="checkbox"/> Video/Photos (During)	On: <u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Video/Photos (After)	On: <u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Video/Photos (30-Day)	On: <u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Property Completion Agreement	Signed: <u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Final Report	Issued: <u> </u> / <u> </u> / <u> </u>	By:

Air Monitoring (as applicable)

<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: <u> </u> / <u> </u> / <u> </u>	By:
Results:		
<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: <u> </u> / <u> </u> / <u> </u>	By:
Results:		
<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: <u> </u> / <u> </u> / <u> </u>	By:
Results:		



Project Resources Inc.

Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID:	2112
Property Address:	4442 Milwaukee
Owner:	Gregorio Soto
Phone:	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	Truck
Item:	Camper shell
Item:	refrige
Item:	Wheelbarrow BBO
Item:	Tires
Item:	Bricks, decorative bricks
Item:	
Item:	



Project Resources Inc.

Items To Be Removed By Contractor During Remediation And Not Replaced
(Use additional sheets as necessary)

Item:
<i>Concrete pad in Backyard</i>
Item:
Item:
Item:
Item:
Item:
Item:

Items To Be Removed By Contractor During Remediation And Replaced
(Use additional sheets as necessary)

Item:
Item:
Item:
Item:
Item:
Item:
Item:



Landscape Inventory
(Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	4547	Square Feet	
Number of trees > 2 inch trunk diameter	5		
Number of trees < 2 inch trunk diameter			
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	N/A		Zones: _____ Heads: _____ Control Valves: _____
Number of and total size of all gardens / flower beds. Attach a sketch of relative sizes and locations.	# Of Beds: _____ # Of Gardens: _____		Ft ² Of Beds: _____ Ft ² Of Gardens: _____



Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials <u>not</u> to be <u>replaced</u> by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds: _____	\$	Total Ft ² Of Beds To Be Replaced With Certificate: <u>17 rose bushes</u>
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of where each plant will be placed by the contractor.	<u>N/A</u>	Each	Only Use For Plants That Are Being Saved and Re-planted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	<u>1752</u>	SF	Total Ft ² Of Sod To Be Laid: <u>1752</u>
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Ft ² : <u>NA</u>	SF	Sod: _____ Brown Mulch: _____ Red Mulch: _____
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch: <u>563</u>	SF	Red: <u>563</u> Brown: _____



Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock: <u>1906</u>	SF	Large: _____ Medium: _____ Small (pea gravel): _____ Driveway Gravel: <u>1906</u>
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover: <u>326</u>		

Additional Comments / Instructions:



Additional Comments / Instructions Continued:

- NO sprinkler system
- Private alley.
- 17 Rose bushes
- no clothesline

☐ Check the box if Owner does not want PRI to document interior foundation walls and possible pre-existing damage. By checking this box PRI is not responsible for any damage done to the interior of house, including foundation cracks or fissures.

☒ I agree

☐ I do not agree

☒ I agree

☐ I do not agree

Eugenio Soto 5-11-05
Owner's Signature Date

Mari Fowler 5-11-05
Contractor's Signature Date

Meagan Redfern

#2112

From: OCARS_Pro@uncc.org
Sent: Thursday, May 12, 2005 8:24 AM
To: Meagan Redfern
Subject: UNCC EMLCFM 2005/05/12 #00014 B0034837-00B NORM NEW

EMLCFM 00014 UNCCb 05/12/05 08:24 AM B0034837-00B NORM NEW STRT LREQ

Ticket Nbr: B0034837-00B

Original Call Date: 05/12/05 Time: 08:24 AM Op: MRE

Locate By Date : 05/16/05 Time: 11:59 PM Meet: N Extended job: N

State: CO County: DENVER City:

Addr: 4442 Street: MILWAUKEE ST

Grids: 03S068W24NW : : Legal: N

Lat/Long: 39.779554/-104.952817 39.779554/-104.951032

: 39.776971/-104.952817 39.776971/-104.951032

Type of Work: SOIL EXCAVATION Exp.: N

Boring: N

Location: LOC ENTIRE LOT*TO INCLUDE ALL EASEMENTS AND CITY

PROPERTY*OWNERS

: PROPERTY INCLUDES HALF OF THE PRIVATE ALLEY BEHIND THE HOME

PLEASE

: LOCATE THIS ALSO

Company : PROJECT RESOURCES INC.

Type: OTHR

Caller : MEAGAN REDFERN

Phone: (303)487-0377

Alt Cont: AMY JAMES

Phone: (303)487-0377

Fax: Email: MREDFERN@PROJECTRESOURCESINC.COM

Done for: EPA/ARMY CORPS OF ENGINEERS

Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA
COMM

ABOVENT= ABOVE NET/MFN

Members ADSTA1 = ADESTA COMM

CDOT06 = CDOT--REGION 6

Members CMSND00= COMCAST - NORTH DENVER

MCI01 = MCI

Members PCNDU0 = XCEL ENERGY-NORTH DENVER

PSND14 = XCEL ENGY--APPT

SCHEDULE-- U

Members QLNCND0= QWEST LOCAL NETWORK (UQ)

QLNCND1= QWEST LOCAL

NETWORK

Members SPRN01 = U.S. SPRINT

TWTEL1 = TIME WARNER

TELECOM

Members WCG01 = WILTEL COMMUNICATION

You are responsible for contacting any other utilities that are not listed above

including the following tier 2 members not notified by the center:

DNVH20 DENVER WATER DEPT (303)628-6666

DNVPR1 DENVER PARKS & REC. (303)458-4839

DTEO01 DNVR TRAFFIC ENG OPERAT. (720)865-4001

WWMG01 WASTEWATER MGMT DIVISION (303)446-3744

SOD

$$\begin{array}{r} 36 \times 12 = 432 \\ 24 \times 12 = 288 \\ 42 \times 14 = 588 \\ 14 \times 12 = 168 \\ 23 \times 12 = 276 \\ \hline 1,752 \end{array}$$

DG

$$\begin{array}{r} 60 \times 8 = 480 \\ 6 \times 21 = 126 \\ 4 \times 21 = 84 \\ 32 \times 38 = 1,216 \\ \hline 1,906 \end{array}$$

R.M.

$$\begin{array}{r} 2 \times 2 = 4 \\ 6 \times 2 = 12 \\ 12 \times 12 = 144 \\ 12 \times 7 = 84 \\ 30 \times 7 = 210 \\ 7 \times 7 = 49 \\ \hline 503 \end{array}$$

Soil

$$\begin{array}{r} 21 \times 12 = 252 \\ 10 \times 2 = 20 \\ 15 \times 2 = 30 \\ 12 \times 1 = 12 \\ 12 \times 1 = 12 \\ \hline 326 \end{array}$$

Total = 4,487 sf.

no city property

dg

soil

sod

rm

$$\begin{array}{r} - 60 \times 8 = 480 \\ - 32 \times 38 = 1,216 \\ - 4 \times 21 = 84 \\ - 6 \times 21 = 126 \\ \hline 1,906 \\ \hline 326 \end{array} \quad \begin{array}{r} 21 \times 12 = 252 \\ 10 \times 2 = 20 \\ 15 \times 2 = 30 \\ 12 \times 1 = 12 \\ 12 \times 1 = 12 \\ \hline 326 \end{array} \quad \begin{array}{r} - 42 \times 14 = 588 \\ 14 \times 12 = 168 \\ 36 \times 12 = 432 \\ 24 \times 12 = 288 \\ 23 \times 12 = 276 \\ \hline 1,752 \end{array} \quad \begin{array}{r} 12 \times 12 = 144 \\ 12 \times 7 = 84 \\ 30 \times 7 = 210 \\ 5 \times 12 = 60 \\ 7 \times 7 = 49 \\ - 2 \times 2 = 4 \\ - 6 \times 2 = 12 \\ \hline 503 \end{array}$$

Total = 4,547

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

Article Addressed to:

GREGORIO SOTO
4442 MILWAUKEE ST
DENVER CO 80216

2. Article Number

(Transfer from service label)

COMPLETE THIS SECTION ON DELIVERY

A. Signature

X *Alyndra Soto*

☐ Agent

☐ Addressee

B. Received by (Printed Name)

C. Date of Delivery

D. Is delivery address different from item 1? ☐ Yes

If YES, enter delivery address below: ☐ No

3. Service Type

☒ Certified Mail

☐ Registered

☐ Insured Mail

☐ Express Mail

☐ Return Receipt for Merchandise

☐ O.D.

4. Restricted Delivery? (Extra Fee)

☐ Yes

7004 2510 0006 141001565

UNITED STATES POSTAL SERVICE



First-Class Mail
Postage & Fees Paid
USPS
Permit No. G-10

- Sender: Please print your name, address, and ZIP+4 in this box •



US Army Corps
of Engineers
Corona, Calif.



VB/I-70 Site Coordination

10 E. 55th Avenue

Denver, CO 80216



PROPERTY INFORMATION

Property ID: 2112
House Number: 4442
Street: MILWAUKEE ST
Address: 4442 MILWAUKEE ST
Unit:
ZIP Code: 80216
Neighborhood: SWANSEA
Zone: R1

Find Record

**OWNER INFORMATION**

Owner Name: GREGORIO SOTO
Mailing Address: 4442 MILWAUKEE ST
Mailing City State Zip: DENVER CO 80216

DECISION CRITERIA

Target Property? Yes
Soil Sampled? Yes
Removal Required? Yes
Removal Complete?

SOIL SAMPLE RESULTS

Phase 3A
Arsenic Decision Value 168
Lead Decision Value 346

OTHER SAMPLE RESULTS

Media Description
Arsenic
Lead

Real Property Records

Date last updated: Friday, February 25, 2005

⌂ Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

[View Map/Historic District Listing for this Property](#)
[Link to property tax information for this property](#)
[Link to property sales information for this neighborhood](#)
[Link to property sales information for all Denver neighborhoods](#)

|< << >> >| Current/Total Records: 908/1034

PROPERTY INFORMATION

Property Type: Residential

Parcel: 0224237003000

Name and Address Information

Legal Description

SOTO,GREGORIO

L 7 & 8 & S 1/2 OF L 6 BLK 20

4442 MILWAUKEE ST

TOWN OF SWANSEA

DENVER, CO 80216

RESIDENTIAL

Property Address:

Tax District

4442 MILWAUKEE ST

DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	29500	2350		
Improvements	117300	9340		
Total	146800	11690	0	11690
Prior Year				
Land	29500	2350		
Improvements	117300	9340		
Total	146800	11690	0	11690

Style: Conversion

Reception No.: 0000167358

Year Built: 1904

Recording Date: 11/03/94

Building Sqr. Foot: 1,269

Document Type: Personal Rep

Bedrooms: 3

Sale Price: 53900

Baths Full/Half: 2/0

Mill Levy: 64.402

Basement/Finished: 140/0

Lot Size: 7,820

TARGET SHEET
EPA REGION VIII
SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1053636

SITE NAME: VASQUEZ BLVD AND I-70

DOCUMENT DATE: 07-16-2005

DOCUMENT NOT SCANNED

Due to one of the following reasons:

- ☐ PHOTOGRAPHS
- ☐ 3-DIMENSIONAL
- ☐ OVERSIZED
- ☒ AUDIO/VISUAL
- ☐ PERMANENTLY BOUND DOCUMENTS
- ☐ POOR LEGIBILITY
- ☐ OTHER
- ☐ NOT AVAILABLE
- ☐ TYPES OF DOCUMENTS NOT TO BE SCANNED
(Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)

DOCUMENT DESCRIPTION:

DVD OF PROPERTY VIDEO

